



JP Specialties, Inc. / Earth Shield® Waterstop

Tech Tips 011

A Simple Repair of Torn Waterstop

by David R. Poole, CSI, ACI

25811 Jefferson Avenue
Murrieta, CA 92562
T 19517637077
F 19517637074
davidp@earthshield.com
<http://www.jp-specialties.com>

Waterstop patch fabricated with same size and shape as damaged Waterstop. (Heat patch and damaged area using field splicing iron; when patch and area become gooey place patch over [on top side] damaged area on Waterstop; allow to cool completely.

